

**Photos of Improvement Works carried out
in connection with Rock Carvings and Inscription**

Rock Carving at Big Wave Bay



Photo 1: Water diversion dam above the Rock Carving



Photo 2: After removal of the water diversion dam

Rock Carving at Shek Pik



Photo 3: Refuse collection point at the footpath leading to the Rock Carving site



Photo 4: After cleaning up of the refuse collection point

Rock Carving on Kau Sai Chau



Photo 5: Shelter of the Rock Carving



Photo 6: Rock Carving after removal of the shelter

Rock Carvings on Cheung Chau



Photo 7: Planter above the Rock Carvings



Photo 8: Planter after removal of some plants



Photo 9: Re-seal of the glass roof to stop the water leakage

Rock Carvings on Cheung Chau



Photo 10: Cement capping at the base of the Rock Carvings




Photo 11: Rock Carvings after removal of the cement capping

Rock Carving at Lung Ha Wan



Photo 12: Protection screen of the Rock Carving



Photo 13: Rock Carving after removal of the protection screen

Rock Inscription at Joss House Bay



Photo 14: Water diversion dam above the Rock Inscription



Photo 15: After removal of the water diversion dam